

Appendix 3

Photographs

Photo 1:
 There was a partial collapse of the SB roof in this area. A timber ceiling has been erected here and on other floors to protect occupants from injury in any future collapse.



Photo 2:
 "Drop-out" at soffit of SB slab overhang outside building. Similar instances have occurred inside the building.



Photo 3:
 Typical hold-down arrangement at existing truss members on L-Block. There appears to be no connection between the timber and the underlying wall.

Photo 4:
 View inside burnt-out section of L-Block. Rubble walls are 16" to 18" thick.

