



Photo 17: New infill walls constructed on the lower floor of the former nurses home.



Photo 18: Dilapidated storage shed at rear of former Nurses Home is a hazard in itself.



Photo 19: Diagonal crack in infill wall at corner of beam soffit.



Photo 20: View of verandah of Baron Wing. The new railing is in structural steel, bolted to the concrete upstand.