



Photo 21: Inadequate hold-down detail on Baron Wing verandah.



Photo 22:
Steel I-beam
reinforcement to
verandah slab.



Photo 23: View of nephrology/cardiology building. Note water tanks sitting on roofs.



Photo 24: A new boundary wall has been constructed on the east of the compound. However, no allowance seems to have been made for the stormwater outfall here.