


FIG. 3



The wall that failed was only minimally supported at the ends by poorly constructed frame walls, the roof was not constructed as a diaphragm.

Several other structures, both conventional construction and adobe, were damaged in the quake.