

FIG. 4



Two adobe structures, the Laundromat and an adjacent Warehouse, were moderately damaged (FIG.4). Damage was confined to the front of both of these structures, to wall sections poorly braced adjacent to storefront openings of large dimension.