

FIG. 5



The Laundromat damage (FIG.5) was confined to the lateral movement of an unbraced wall adjacent and untied to the front wall.