


FIG. 6



Damage to the parapet wall above the storefront opening of the warehouse (FIG.6) appears to have been concentrated in the small cross sectional area at the connection of the front and side wall. No bond beam was evident on this structure.