


FIG. 7



Extensive damage to the Third Street residence (FIG.7) was concentrated at the ground level (FIG.8). Carefull examination revealed extremely wet adobe within the wall at the point of failure.

FIG. 8

