

Photo 25:
Electrical cabling
being placed
underground for new
L-Block.



Photo 27:
New lean-to shelter roof between Baron Wing and L-Block. The bridge connecting the two buildings is in the background.



Photo 26:
Additional free-standing storage tanks atop roof of existing concrete water tank. They are not fixed to the concrete.



Photo 28:
Inadequate details on shelter roof (previous photo). Steel column has actually been split at the topmost four corners. It is nailed to timber beam on the underside and bolted on the sides. Some bolts were missing.