



Photo 31: View of repaired water tank with additional storage drums.

Photo 32: View along verandah of renovated L-Block. The timber beam on the outside edge of the balcony sits on cast iron columns. There is no obvious connection between the two members.



Photo 29: View of western side of compound. The hospital boundary (note fence on right of picture) has been moved inward to accommodate a new highway to be constructed close to the line of the existing road. The boiler and standby generator rooms remain in the same state as in 1993.



Photo 30: View of the chest wing.