



Photo 33: View of burnt-out section of L-Block.

Photo 34: View of poorly constructed wall inside L-Block. Apparently this was once part of the X-ray room. a stone wall forms the other face. The cavity between the two may have been filled with sand.




Photo 35: View of NE corner of L-Block. New construction is on the far right.