

Valve House



Slope protection works had been completed before the disaster and no damage was caused to the valve house.