



Damages near the eastern head works. The control house was completely collapsed and the generator house was inundated and partially damaged. River banks and main canal were washed away.



East Main Canal immediately downstream of head works.



Damaged left bank between Barrage and East-West Highway

Inundation and siltation at the camp of Bagmati Irrigation Project



Damage to houses on the right bank of Bagmati River