



Photo 5: Gable-end wall to right formed part of the old operating theatre in the L-Block. It is to be partially demolished.

Photo 7: Tree with adjacent utility lines. The tree was being trimmed at the time this photograph was taken.



Photo 6: Spalling along the edge of the concrete slab on the Administration Building.



Photo 8: The two closer buildings on the right (near the entrance to the hospital) are temporary structures erected to accommodate facilities (including a ward) lost during the fire.