



Photo 13: New structure erected adjacent the geriatric ward. Used to house non-perishable stores.



Photo 15: New small structure on the left contains hospital autoclave (used to sterilise equipment). Pipes from the boiler feed the autoclave and hospital laundry. The autoclave was located inside the L-Block until the fire.



Photo 14: View of renovated and to-be-renovated sections of the L-Block. Cyclone washers have been used on the newer sheeting. Note roof of the "link" in the foreground.



Photo 16: New extension at NW end of L-Block under construction.