



FIG. 9

A two storied brick building right on the ground rupture, after Gediz (Western Turkey, 1970) earthquake. The wall at ground floor absorbed considerable amounts of deformation, leaving the upper story practically intact, thanks to the horizontal timber bond beams provided at various levels. Although the material of the wall is not adobe, it gives an idea as to the effectivity of bond beams in such buildings.