



Upstream of Agra Khola at Chisapani where a major landslide is in active stage. Numerous slope failures are also seen in adjacent mountain range.





Slope failures and gully erosion in Mitrang Village of Makwanpur District on the Agra Khola catchment



Numerous slope failures in granite formation zone near to Palung of Kulekhani catchment in Mahabharat Range