



Numerous cracks at Chisapani landslide on the top of Agra Khola. Most of the cracks are observed as fresh.



This photo shows devastated situation of upstream of Belkhu Rivers.



These photos show devastated situation of upstream of Agra, Belkhu and Malekhu Khola.