

7. SINDHULI DISTRICT



Landslide along MBT.
Irrigation channel damaged by landslide in Sindhuli.

Marin Khola



Vast river course of Marin Khola



Sediment discharge from a tributary of Marin Khola.



Scouring of river terrace by flood of Marin Khola.